



STEP 1



OVERLAP CABLES BY 500mm MINIMUM, MARK CENTRE LINE AND CUT AS PER DIAGRAM. CLEAN CABLE SURFACES AND COVER WITH PLASTIC WRAP ABOUT 1.5m EACH SIDE OF THE CENTRE LINE.

STEP 2




CABLE	35 sq.mm 11kV	400 sq.mm 11kV	95 sq.mm 11kV 35 sq.mm 22kV	240 sq.mm 11kV 120 sq.mm 22kV
DIM A mm	275	325	275	325
TERMIMESH SIPE	1000x250	1100x300	1000x280	1100x320

REMOVE OUTER SHEATH, NYLON AND INNER SHEATH TO A DISTANCE 'A' FROM THE CENTRE LINE OF THE LH CABLE, AND 'A' + 150mm FROM THE CENTRE LINE OF THE RH CABLE.

BEND BACK THE LONG SCREEN WIRES OF THE LH CABLE AND SECURE WITH A SPIRAL WRAP OF PVC TAPE. DON'T TAPE THE BEND DOWN - IT WON'T STRAIGHTEN EASILY LATER. REMOVE WATER SWELLABLE TAPE. ON THE RH CABLE MARK THE SCREEN WIRES WITH A TEXTA AT A DISTANCE 'A' FROM THE CENTRE LINE AND CUT THE WIRES WITH SIDE CUTTERS. REMOVE WATER SWELLABLE TAPE. PVC TAPE OVER THE ENDS OF THE WIRES.

PLACE THE LARGE OUTER HEAT SHRINK TUBE OVER THE LH CABLE. TEMPORARILY PLASTIC WRAP THE SEMI-CON AND SCREEN WIRES ON THE RH CABLE AND CAREFULLY PARK THE INNER JOINT SLEEVE SET. COVER THE PARKED TUBES WITH PLASTIC WRAP UNTIL NEEDED.


STEP 3



CUT CABLES AT THE CENTRE LINE. CAREFULLY REMOVE SEMI-CONDUCTIVE SCREEN (SEE INSTRUCTION ON DRAWING S02-02-02-21) FROM BOTH CABLES TO THE DIMENSIONS SHOWN. REMOVE INSULATION FROM CONDUCTORS FOR A DISTANCE 'X' EQUAL TO HALF THE CONNECTOR LENGTH + 5mm. CUT A 3mm (MAX) BEVEL ON THE INSULATION ENDS.

FOR STEPS 6-11 SEE DRG S02-02-02-24

STEP 4




WET WIRE BRUSH (ie UNDER A LIGHT FILM OF JOINTING COMPOUND) THE CONDUCTORS. JOIN CONDUCTORS WITH THE APPROPRIATE CONNECTOR AND DIE, REMOVE ANY BURRS, AND THOROUGHLY CLEAN OFF EXCESS GREASE FROM CONNECTOR AND CABLE INSULATION. THOROUGHLY CLEAN THE CABLE INSULATION (SEE INSTRUCTION ON DRAWING S02-02-02-20) USING THE CLEANING PADS SUPPLIED IN THE JOINT KIT. DON'T RE-USE PADS. DON'T HANDLE THE INSULATION FROM NOW ON!

USING THE YELLOW/BROWN MASTIC TAPE, STRETCHING IT TO HALF ITS ORIGINAL WIDTH, FILL THE GAPS BETWEEN THE CONNECTOR AND CABLE INSULATION, CONTINUING OVER THE CONNECTOR AND OVERLAPPING THE CABLE INSULATION AT EACH END BY 5mm. DON'T TOUCH THE MASTIC AFTER IT'S APPLIED! DO NOT USE TOO MUCH MASTIC. IF THE CONNECTOR DIAMETER IS GREATER THAN THE INSULATION DIAMETER ONLY A THIN LAYER IS NEEDED. IF THE CONNECTOR DIAMETER IS SMALLER THEN USE ONLY SUFFICIENT TO MATCH THE CABLE DIAMETER. A SMEAR OF SILICONE GREASE ON YOUR FINGERS WILL PREVENT THEM FROM STICKING TO THE MASTIC.

CHECK THAT ALL SURFACES ARE CLEAN (LOOK UNDERNEATH!) AND THAT NO DIRT OR MOISTURE CAN CONTAMINATE THE INSIDE OF THE TUBES.

STEP 5



PLACE THE BLACK STRESS CONTROL TUBE CENTRALLY OVER THE JOINT. STARTING AT THE CENTRE SHRINK THE TUBE TOWARDS ONE END AND THEN TOWARDS THE OTHER END UNTIL FULLY SHRUNK. APPLY HEAT EVENLY THROUGHOUT THE PROCESS. WHEN COMPLETED ADHESIVE WILL FLOW FROM THE ENDS, WIPE OFF EXCESS. Don't stop for smoko now!

JOINT KIT STOCK CODES - REFER DRAWING S02-01-02-03
COMPRESSION LINKS - REFER DRAWING S02-02-02-17

NO	DESCRIPTION	DRN	DATE	CKD	APPD
1	SUPERSEDED	A. T.	DEC '12	B. C.	B. C.
AMENDMENTS					



DES	-	POWER STANDARD DRAWING		
DRN	J.A.L.	CABLE JOINTING & TERMINATIONS		
CKD	A.T.	SIGMAFORM JOINTING INSTRUCTIONS (SHEET 1 OF 2)		
APPD	P.J.D.	11/22kV XLPE CABLE		
SCALE	N.T.S.	A3	DRAWING NUMBER	S02-02-02-23
ISSUED	DEC '95			
ALL DIM.	IN mm	DRAWING NUMBER		S02-02-02-23
DRAFTING STANDARD TO A.S.1100		CAD PRODUCT - DO NOT AMEND MANUALLY		AMDT