

Date: Thursday 17 March 2011 **Issue number:** 2011-1
Issue(s): Release of CCTV Inspection Guidelines for newly constructed sewers
Audience: Proponents, Project Managers, Construction Supervisors, Constructors

What's new?

Power and Water Corporation (PWC) has released CCTV Inspection Guidelines for newly constructed sewers.

These guidelines are based on the Water Services Association of Australia (WSAA) Conduit Inspection Reporting Code of Australia (WSA 05) however the guidelines are designed to be used without reference to WSA 05.

The guidelines can be downloaded from the PWC website at powerwater.com.au/water_services_connection_code

How can I notify Power and Water of ambiguities in the guidelines?

Stakeholders are encouraged to provide feedback and suggestions that will make the guidelines easier to use. Power and Water will endeavour to respond to all feedback within three weeks.

Feedback can be submitted using the online form available at powerwater.com.au/water_services_connection_code_feedback

Word or PDF documents can be attached where necessary.

How can I get more information?

PWC's Service Development administers the Connection Code and associated activities. This includes the asset creation design and construction process for the Corporation's water supply and sewerage infrastructure. The Connection Code and Infrastructure Design Approval Process internet pages are available on our internet at powerwater.com.au/water_services_connection_code

Contacts

Northern Region

Service Development North
Location: Ben Hammond Complex
Iliffe Street, Stuart Park
Postal: PO Box 37471
Winnellie NT 0821
Phone: (08) 8995 5802
Fax: (08) 8924 5121
LandDevelopmentNorth@powerwater.com.au

Southern Region

Service Development South
Location: Sadadeen Valley
Berger Court, Alice Springs
Postal: PO Box 1521
Alice Springs NT 0871
Phone: (08) 8951 7312
Fax: (08) 8951 7347
LandDevelopmentSouth@powerwater.com.au