

Connection Code Bulletin 2008 – 4

Issue/s: Confirmation of Sewer CCTV inspection requirement
Audience: Proponents, Project Managers, Designers, Construction Supervisors and Constructors
Date: 1st October 2008

What has changed?

As per connection code bulletin 2008-1, CCTV inspections will now be mandatory as part of the sewer acceptance process.

To minimise or avoid confined space entry to the sewer system during sewerage handover inspections, a number of changes have been made. A full CCTV inspection of the new sewerage infrastructure will be undertaken by the proponent prior to handover.

It is proposed that the new procedures require:

- 1) All new sewer assets be CCTV inspected prior to handover inspection
- 2) Power and Water standard documentation be used (where published). The new technical document to be used for CCTV inspection reporting can be found at http://www.powerwater.com.au/powerwater/business/connectioncode/html/tech_requirements.htm

The following documentation will be required prior to the handover inspections of new sewerage assets:

- 'As constructed' drawings highlighting the location of the sewer lines inspected
- Certification that all defects noted at CCTV inspection have been rectified
- Completed CCTV Inspection form, complete with photos and videos as identified on the form
- Any other relevant photos and videos taken at the inspection
- For new sewer lines of less than 100 metres please confirm requirements with Services Development prior to undertaking a CCTV inspection.

List of available CCTV inspectors

This list does not preclude other companies from providing CCTV services.

Those currently available to undertake CCTV sewer inspections include:

Northern Region

- John Mousellis
- Renoflow

Southern Region

- Centre Plumbing
- SDA

As a guide for budget purposes, a cost of \$4.50/metre should be allowed.

How can I get more information on the changes?

Further information can be obtained by contacting Ella Patterson on (08) 8924 5215 or ella.patterson@powerwater.com.au

Northern Region

Service Development North
Water Services Operations Centre (Bunker)
Iilfe Street, Stuart Park
Postal Address: PO Box 37471
WINNELLIE NT 0821
Telephone: (08) 8924 5282
Facsimile: (08) 8924 5287
LandDevelopmentNorth@powerwater.com.au

Southern Region

Service Development South
Sadadeen Valley
Berger Court, Alice Springs
Postal Address: PO Box 1521
ALICE SPRINGS NT 0871
Telephone: (08) 8951 7312
Facsimile: (08) 8951 7347
LandDevelopmentSouth@powerwater.com.au

